



Technical Bulletin

Trio Motion Technology Ltd.
Shannon Way,
Tewkesbury
Glos. GL20 8ND U.K.

Tel: 01684 292333
Fax: 01684 297929
Email: apps@triomotion.com
Web: www.triomotion.com

Doc No.: TN20-13
Version: 1.0
Date: 2 October, 1998
Subject: MC216 with Comms daughter boards + axis expansion

Applicability: Serial No's <= P140-00018

Details:

A conflict has been identified with MC216 units listed above, such that if fitted with both axis expansion and communications daughter boards (i.e. CANBus Servo boards) the unit will fail to function correctly.

A minor modification is required to rectify the problem. Any MC216 unit that is required to use both axis expansion and CAN Daughter boards should be returned to Trio for modification.

If this combination of options is not required then the unit does not require the modification to be made.